


# Shuttle



For fully automated movement of parts for automated presses.

- Quick coupler for fixture – **short changeover time**
- Installed directly on the floor – **simple to install**
- Few component parts – **easy to maintain**

# Shuttle


AP&T shuttles are used for fully automated movement of parts in automated presses. Shuttle conveyors can also be used to feed parts into or out of systems.

**The standard version includes:**

- Harting contact at quick coupler
- Floor stand
- Quick coupler for fixture



Shuttle fixture



Shuttle conveyor

**Options:**

- Turning device
- Rotary motion/Tilt
- Wheel set

Type	Standard stroke length mm	Max. stroke length mm	Max. load incl. fixture kg	Max speed mm/s
	X			
<b>Shuttle 20</b>	1,000	6,000	20	5,000
<b>Shuttle 20 double</b>	1,000	6,000	40	5,000
<b>Shuttle 40</b>	2,000	4,600	40	5,000
<b>Shuttle 60</b>	2,000	4,600	60	5,000
<b>Shuttle 120</b>	2,000	4,600	120	5,000
<b>Shuttle conveyor</b>	-	-	25	500